



Service Bulletin

Subject: Side Marker LED's on Colorado Highmark Flares

Applicable Models: Chevrolet Colorado's equipped with AEV Highmark fender flares.

Condition: All side marker lights in the flares inoperable after install

Diag/Repairs: Some work orders of the light harnesses had the LED's installed backwards. LED's only work with current flowing in one direction, so if all lights in the harness fail to illuminate try reversing the wires on one of the LED's. If it lights up, do the same for the others.