



## Service Bulletin

**Subject:** Ram 1500 EcoDiesel ProCal quirk

**Applicable Models:** 2013-2018 Ram 1500's equipped with the EcoDiesel engine using the switch style ProCal

**Condition:** Tire size programming won't take

**Diag/Repairs:** The EcoDiesel trucks will not honk the horn while programming tire size, instead they will flash the brake warning light on the instrument cluster. This only effects EcoDiesels and only while doing tire size, all other program functions will honk the horn normally, and all other engines will honk the horn while programming tire size.