



## Service Bulletin

**Subject:** Warning lights on after programming tire size

**Applicable Models:** 2019+ Ram HD's using the AEV ProCal Snap

**Condition:** After programming tire size, multiple warning lights are illuminated related to the ABS/vehicle speed systems, such as Service 4WD, Traction Control Inop, Stability Control Off, etc...

**Diag/Repairs:** When programming tire size on the Rams, many customers hold the brake pedal and RES button too long while waiting for the horn to honk. The instructions state that when programming tire size, hold until the brake warning light flashes on the instrument cluster and release immediately. This is often missed which will result in an error while programming which will then cause the multiple warning lights. To fix, simply program tire size again and release the pedal and button when the brake light flashes. Some customers may still have a Check Engine light on after programming, but that will typically go away after a few drive cycles.